

B.Well+

Caring for everyone

Instructions for use

PRO-165 white/black

Electronic
Personal Scale

EN



PRO

MED

TECHNO

1. INTRODUCTION

Dear consumer!

**We congratulate you with a B.Well electronic personal scale buying!
Thank you for choosing our product!**

Product was developed, verified and supervised by B.Well Swiss AG, Switzerland. Applied Swiss control system assures high quality, endurance and safety of all B.Well products. This new electronic personal scale allows you to evaluate your body weight. Capacity 180 kilos, divided into 100 grams.


Please read through these instructions carefully so that you understand all functions and safety information. We want you to be happy with your B.Well product.

The B.Well company is guaranteeing that this scale is made of high quality materials and meets current national and international safety standards.

2. OPERATING INSTRUCTION

Place the scale on a hard, flat surface will ensure on the greatest accuracy and repeatability. Soft, inaccurate flooring (e.g. rugs, carpets, linoleum) can cause the scale to give uneven reading of your weight.

Stepping onto the scale then the number on LCD flash 3 times, that is the weighing result of your body (step onto the scale with your feet parallel and weight equally distributed).



Stand still while the scale measures your weight.

Always weigh yourself on the same scale each day at the same time, preferably undressed and before breakfast.

The surface of the scale can be slippery, if wet.

3. USING THE SCALE FOR THE FIRST TIME

How to insert the battery

This scale operates with one replaceable lithium battery.

Please insert batteries or remove the insulating strip from the battery contacts before using. Replace the batteries when the "Low Battery Indicator" shows.

If the scale would not be used in a long period, please take the battery out, and make sure there is nothing on the scale.

KG / LB / ST Switch


Located at the bottom of the scale, this switch allows you to choose the unit of measurement for weighing: kg, lb or st.

Use as simple scale

1. In order to get accurate measurements, place the scale on a firm level floor.
2. Step onto the scale and wait without moving; after a few seconds, the display screen will show your weight.
Do not lean on anything while being weighed as this could alter the reading.



UNIT



- Step off the scale, the display screen will continue to show your weight for a few seconds then it will turn off automatically.
- When the scales are overloaded (over 180 kg/396 lb/28 st), the following will appear on the screen:



4. SAFETY, CARE, ACCURACY TEST AND DISPOSAL

- This device may only be used for the purposes described in these instructions. The manufacturer cannot be held liable for damage caused by incorrect application.
- This device comprises sensitive components and must be treated with caution. Observe the storage and operating conditions described in the "Technical Specifications" section.
- Protect the scale against knocks, damp, dust, chemicals, drastic changes in temperature, electromagnetic field and source of heat that are too near.
- Never open this device.
- If the scale would not be used in a long period, please take the battery out, and make sure there is nothing on the scale.
- Keep packaging material away from children!
- Never step onto the outer edge of the scale with one foot as this could cause the scales to tip!

Device care

You can clean the scale with a damp cloth and a little washing up liquid, if required. Never immerse the scale in water or rinse it under running water.

Disposal

Batteries and electronic devices must be disposed of in accordance with the locally applicable regulations, not with domestic waste.

5. TECHNICAL SPECIFICATIONS

- Max capacity: 180 kg/396 lb/28.8 st
- Division: 100 g/0.2 lb
- Accuracy:
 - ±0.3 kg for measurement range 3 kg to 50 kg
 - ±0.5 kg for measurement range 51 kg to 100 kg
 - ±0.7 kg for measurement range 101 kg to 150 kg
 - ±0.8 kg for measurement range 151 kg to 180 kg
- LCD display: 73 × 34 mm
- Dimension of scale: 300.5 × 300.5 × 17.5 mm
- 6 mm tempered safety glass platform
- Equipped with high strain gauge sensors
- Auto on function
- Weighing unit switch between kg/lb/st
- Automatic zero and switch off
- Low battery and overload indication
- Battery CR2032 × 1PC

Operation environment:

Temperature: +10°C ~ +40°C

Humidity: <80%

Storage and transportation environment:

Temperature: -20°C ~ +50°C

Humidity: <90%

Technical alterations reserved.

6. SYMBOL INFORMATION



Follow instructions before use



Manufacturer's Name



Article number



Serial number



Type BF equipment



Disposal for separate collection



Operating condition, temperature 10°C ~ 40°C



Storage condition, teperature -20°C ~ 50°C



CE mark



Keep dry

7. WARRANTY INFORMATION

Warranty period is 1 years from the date of purchase. This warranty doesn't cover any damages caused by improper using, and also battery and packaging. When a manufacturing defect is revealed during the warranty period a faulty unit would be repaired or, if repairing is impossible, replaced with another one.

The manufacturer may change units partially or completely if necessary, without prior notice.

The date of manufacture of the device is specified in the LOT number indicated on the device. The first two digits indicate the month, and the following four digits indicate the year of production.

B.Well 
Caring for everyone

 **B.Well Swiss AG**

Bahnhofstrasse 24,
9443 Widnau,
Switzerland

www.bwell-swiss.ch